How to cut a DW-pipe element

1 Pull apart inner and outer tube



2 Mark required length
(The pipe ends with the female part will be needed!)



3 Cut inner and outer tube

4 Debur cutting edges

5 Cut insulation

(Cut the same length off the Insulation as the length of the waste part of inner or outer tube)

6 Put back together tubes and insulation



BEFORE

AFTER